

## Non-Operating Stationary Shade Primarily Used For Transom Windows And North Facing Windows

## Hardware Included

**Self Tapping Screws** for Aluminum



Wood Screws (If Requested)



## **Tools Required**

Drill 1/4" Hex Head



## **Install Shade**

Center and screw stationary valance directly to underside of window frame



